



Alvis Cars - Model Register

The following register of cars has been produced by Wayne Brooks
for the Alvis Archive Trust from original Alvis factory records
for the personal use of Alvis owners and enthusiasts

Enquiries for further information on individual cars can be made on

<https://alvisarchive.com/ask-a-question/>

July 2021

Bowcliffe Hall, Bramham, Wetherby, West Yorkshire LS23 6LP
alvisarchive@btinternet.com
www.alvisarchive.com

TB14 Register

Model	LHD	Coachbuilder	Body No.	Body Style	Chassis	Registration	Despatched		
TB14		A. P. Metalcraft	1001	2 Seater Sports	23500	JVC 458	16	5	1950
TB14		A. P. Metalcraft	1003	2 Seater Sports	23501	AUS	6	3	1950
TB14		A. P. Metalcraft	1005	2 Seater Sports	23502	HK	23	5	1950
TB14		A. P. Metalcraft	1006	2 Seater Sports	23503	AUS	6	4	1950
TB14		A. P. Metalcraft	1007	2 Seater Sports	23504	AUS	17	5	1950
TB14		A. P. Metalcraft	1008	2 Seater Sports	23505	AUS	1	5	1950
TB14		A. P. Metalcraft	1010	2 Seater Sports	23506	T	7	4	1950
TB14		A. P. Metalcraft	1012	2 Seater Sports	23507	AUS	9	5	1950
TB14		A. P. Metalcraft	1013	2 Seater Sports	23508	T	12	4	1950
TB14		A. P. Metalcraft	1017	2 Seater Sports	235f260	AUS	22	5	1950
TB14		A. P. Metalcraft	1021	2 Seater Sports	23510	PK	22	5	1950
TB14		A. P. Metalcraft	1023	2 Seater Sports	23511	AUS	23	5	1950
TB14	lhd	A. P. Metalcraft	1004	2 Seater Sports	23512	B	12	3	1950
TB14		A. P. Metalcraft	1025	2 Seater Sports	23513	GKW 294	26	5	1950
TB14		A. P. Metalcraft	1026	2 Seater Sports	23514	NUG 803	9	6	1950
TB14		A. P. Metalcraft	1027	2 Seater Sports	23515	MZ 9788	13	6	1950
TB14		A. P. Metalcraft	1028	2 Seater Sports	23516	NAF 1	26	5	1950
TB14		A. P. Metalcraft	1029	2 Seater Sports	23517	NHT 11	7	6	1950
TB14		A. P. Metalcraft	1030	2 Seater Sports	23518	LLF 999	14	6	1950
TB14		A. P. Metalcraft	1031	2 Seater Sports	23519		14	6	1950
TB14	lhd	A. P. Metalcraft	1009	2 Seater Sports	23520	CH	1	3	1950
TB14	lhd	A. P. Metalcraft	1002	2 Seater Sports	23521	GBZ	7	3	1950
TB14	lhd	A. P. Metalcraft	1011	2 Seater Sports	23522	S	18	4	1950
TB14	lhd	A. P. Metalcraft	1014	2 Seater Sports	23523	S	18	4	1950
TB14	lhd	A. P. Metalcraft	1015	2 Seater Sports	23524	S	25	4	1950
TB14		A. P. Metalcraft	1020	2 Seater Sports	23525	PK	22	5	1950
TB14		A. P. Metalcraft	1032	2 Seater Sports	23526	FBK 732	16	6	1950
TB14		A. P. Metalcraft	1033	2 Seater Sports	23527		22	6	1950
TB14		A. P. Metalcraft	1035	2 Seater Sports	23528	KNY 819	28	6	1950
TB14		A. P. Metalcraft	1036	2 Seater Sports	23529		7	7	1950
TB14		A. P. Metalcraft	1037	2 Seater Sports	23530	DHE 252	28	6	1950
TB14		A. P. Metalcraft	1040	2 Seater Sports	23531	T	9	8	1950
TB14		A. P. Metalcraft	1041	2 Seater Sports	23532	ERG 1	19	7	1950
TB14		A. P. Metalcraft	1042	2 Seater Sports	23533	T	9	8	1950
TB14		A. P. Metalcraft	1043	2 Seater Sports	23534	SGP	1	8	1950
TB14	lhd	A. P. Metalcraft	1016	2 Seater Sports	23535	RL	16	5	1950
TB14	lhd	A. P. Metalcraft	1022	2 Seater Sports	23536	LGX 770	14	6	1950
TB14	lhd	A. P. Metalcraft	1024	2 Seater Sports	23537	GBZ	6	6	1950
TB14	lhd	A. P. Metalcraft	1018	2 Seater Sports	23538	CDN	8	5	1950
TB14	lhd	A. P. Metalcraft	1034	2 Seater Sports	23539	PE	28	6	1950
TB14	lhd	A. P. Metalcraft	1019	2 Seater Sports	23540	CDN	26	5	1950
TB14		A. P. Metalcraft	1044	2 Seater Sports	23541	KLJ 518	17	7	1950
TB14		A. P. Metalcraft	1045	2 Seater Sports	23542	MTV 550	13	7	1950
TB14		A. P. Metalcraft	1047	2 Seater Sports	23543	LLK 799	21	7	1950
TB14		A. P. Metalcraft	1048	2 Seater Sports	23544	OEH 564	24	7	1950
TB14		A. P. Metalcraft	1049	2 Seater Sports	23545	HSG 97	25	7	1950
TB14		A. P. Metalcraft	1052	2 Seater Sports	23546	BVV 423	26	7	1950

TB14 Register

Model	LHD	Coachbuilder	Body No.	Body Style	Chassis	Registration	Despatched		
TB14		A. P. Metalcraft	1053	2 Seater Sports	23547	JP 8870	25	7	1950
TB14		A. P. Metalcraft	1054	2 Seater Sports	23548	GAV 444	31	7	1950
TB14		A. P. Metalcraft	1055	2 Seater Sports	23549	T	9	8	1950
TB14		A. P. Meatlcraft	1059	2 Seater Sports	23550	MWJ 469	17	8	1950
TB14		A. P. Metalcraft	1058	2 Seater Sports	23551	ORB 244	28	7	1950
TB14		A. P. Metalcraft	1060	2 Seater Sports	23552	SGP	31	7	1950
TB14	lhd	A. P. Metalcraft	1038	2 Seater Sports	23553	EFR 698	29	6	1950
TB14	lhd	A. P. Metalcraft	1039	2 Seater Sports	23554		7	7	1950
TB14	lhd	A. P. Metalcraft	1056	2 Seater Sports	23555	USA	9	8	1950
TB14	lhd	A. P. Metalcraft	1050	2 Seater Sports	23556	BDJ 239	24	7	1950
TB14	lhd	A. P. Metalcraft	1046	2 Seater Sports	23557	MTD 6	13	7	1950
TB14	lhd	A. P. Metalcraft	1051	2 Seater Sports	23558	JGB 659	21	7	1950
TB14		A. P. Metalcraft	1061	2 Seater Sports	23559	MFM 563	16	8	1950
TB14		A. P. Metalcraft	1062	2 Seater Sports	23560	NUM 517	18	8	1950
TB14		A. P. Metalcraft	1081	2 Seater Sports	23561	KTG 373	18	8	1950
TB14		A. P. Metalcraft	1066	2 Seater Sports	23562	JGB 444	1	9	1950
TB14		A. P. Metalcraft	1075	2 Seater Sports	23563	OPG 249	7	9	1950
TB14		A. P. Metalcraft	1067	2 Seater Sports	23564	HUS 471	28	8	1950
TB14		A. P. Metalcraft	1074	2 Seater Sports	23565	LXA 451	29	8	1950
TB14		A. P. Metalcraft	1079	2 Seater Sports	23566	GKW 940	13	9	1950
TB14		A. P. Metalcraft	1076	2 Seater Sports	23567	GUN 432	15	9	1950
TB14		A. P. Metalcraft	1082	2 Seater Sports	23568	BSN 499	14	9	1950
TB14		A. P. Metalcraft	1086	2 Seater Sports	23569	AEC 421	13	10	1950
TB14		A. P. Metalcraft	1077	2 Seater Sports	23570	LFJ 212	11	9	1950
TB14		A. P. Metalcraft	1063	2 Seater Sports	23571	EFE 671	14	9	1950
TB14		A. P. Metalcraft	1080	2 Seater Sports	23572		19	9	1950
TB14		A. P. Metalcraft	1083	2 Seater Sports	23573	OEH 819	21	9	1950
TB14		A. P. Metalcraft	1084	2 Seater Sports	23574	ECL 123	22	9	1950
TB14		A. P. Metalcraft	1064	2 Seater Sports	23575	HUS 384	22	8	1950
TB14		A. P. Metalcraft	1078	2 Seater Sports	23576	MTV 824	14	9	1950
TB14		A. P. Metalcraft	1087	2 Seater Sports	23577	GWM 437	3	11	1950
TB14		A. P. Metalcraft	1065	2 Seater Sports	23578	AHG 355	24	8	1950
TB14		A. P. Metalcraft	1088	2 Seater Sports	23579	HYS 615	2	11	1950
TB14	lhd	A. P. Metalcraft	1057	2 Seater Sports	23580	HUS 214	28	7	1950
TB14		A. P. Metalcraft	1093	2 Seater Sports	23581		9	11	1950
TB14		A. P. Metalcraft	1085	2 Seater Sports	23582	EDB 677	28	9	1950
TB14	lhd	A. P. Metalcraft	1073	2 Seater Sports	23583	RPU 584	29	9	1950
TB14	lhd	A. P. Metalcraft	1068	2 Seater Sports	23584	LND 570	29	9	1950
TB14	lhd	A. P. Metalcraft	1069	2 Seater Sports	23585	JGB 56	13	10	1950
TB14	lhd	A. P. Metalcraft	1071	2 Seater Sports	23586	HYS 187	10	10	1950
TB14	lhd	A. P. Metalcraft	1070	2 Seater Sports	23587	EHS 844	6	10	1950
TB14		A. P. Metalcraft	1090	2 Seater Sports	23588	ECL 265	7	11	1950
TB14		A. P. Metalcraft	1089	2 Seater Sports	23589	ONW 119	23	10	1950
TB14		A. P. Metalcraft	1091	2 Seater Sports	23590	LXA 453	3	11	1950
TB14		A. P. Metalcraft	1094	2 Seater Sports	23591	HWS 43	13	11	1950
TB14	lhd	A. P. Metalcraft	1072	2 Seater Sports	23592		3	11	1950
TB14		A. P. Metalcraft	1092	2 Seater Sports	23593	NPP 631	3	11	1950

TB14 Register

Model	LHD	Coachbuilder	Body No.	Body Style	Chassis	Registration	Despatched		
TB14		A. P. Metalcraft	1095	2 Seater Sports	23594		14	11	1950
TB14		A. P. Metalcraft	1096	2 Seater Sports	23595	LKF 888	12	12	1950
TB14		A. P. Metalcraft	1097	2 Seater Sports	23596	LXU 529	1	12	1950
TB14		A. P. Metalcraft	1098	2 Seater Sports	23597	LVM 186	14	12	1950
TB14		A. P. Metalcraft	1099	2 Seater Sports	23598	JGB 56	11	12	1950
TB14		A. P. Metalcraft	1100	2 Seater Sports	23599		12	12	1950